

From: [Jonathan Carroll](#)
To: [Moore, Gary](#)
Subject: Fw: Tank 16 Interior
Date: Monday, September 23, 2013 9:39:35 AM

You knew about this before I did. PROBLEM!!!

----- Forwarded Message -----

From: "Moore, Gary" <Moore.Gary@epa.gov>
To: Jonathan Carroll <jcarroll@lazarusenergy.com>; Steve Wilson <swilsonwse@gmail.com>; Alonzo Arredondo <aarredondo@trcsolutions.com>
Sent: Friday, September 20, 2013 5:19 PM
Subject: Tank 16 Interior

Jonathan

I went by the site on september 16 to see progress. See the picture of some of the holes in tank 16 botton. Those are welding rods showing all the holes.

Was the tank botton evaluated an by who? Was it scanned for metal thickness on areas not showing visible sign of corrossion? I would like a copy sent to me.

Gary Moore



9568175